

The following site is being submitted for inclusion into the GIS registry:

This is a:	New Submittal
BRRTS ID (no dashes):	0315002153
Comm # (no dashes):	54235341456
County:	Door
Region:	Commerce
Site name:	Brunswick Station
Street Address:	56 N Madison Ave
City:	Sturgeon Bay
Closure Date	2000-09-28
Closure Conditions:	met
Offsite contamination?	No
Right-of-way contamination?	No
Contaminated media:	Groundwater
GPS Coordinates (meters in the WTM91 projection)	
Easting (X):	726782.45730386
Northing (Y):	487361.374073638
Submitted by:	Cheryl Nelson

Checklist

- ☒ Final Closure Letter
- ☒ Copy of recorded deed Instrument for any property with GW >NR140 ES
- ☒ General Location Map
- ☒ Detailed Location Map showing property boundaries, buildings, etc for properties with GW >NR140 ES
- ☒ Latest Map(s) showing extent or outline of current GW plume
- ☒ GW flow direction
- ☒ MW(s) and/or potable wells
- ☒ Latest Table of GW results

September 28, 2000

City of Sturgeon Bay
Attn: Jay Krauss
P.O. Box 47
Sturgeon Bay, WI 54235

RE: **CASE CLOSURE Approved**
Brunswick Station, 56 N. Madison Avenue, Sturgeon Bay, WI
COMMERCE #54235-3414-56

Dear Mr. Krauss:

The Department is in receipt of documentation that the conditions necessary for site closure detailed in the **CASE CLOSURE CONDITIONAL UPON RECEIPT OF DOCUMENTATION** letter dated May 11, 2000 have been met. The Department considers that no further action is necessary and has updated our database to reflect this closure.

Thank you for your efforts in restoring Wisconsin's environment. If you have any additional questions, please contact me at 920-424-0046.

Sincerely,



Robert H. Klauk, P.G.
Hydrogeologist
Site Review Section
Bureau of PECFA

cc. Joe Ramcheck – Envirogen
File – pf\pecfa\543\54235\341456\Close2.doc

605959

Document Number

733 PAGE 577

NOTICE OF CONTAMINATION TO
PROPERTY

RECEIVED FOR RECORD
REGISTER OF DEEDS
DOOR COUNTY

'00 AUG 22 AM 8 36

Marilyn Jardin

Legal Description of the Property: In re:

The North 50 feet of Lots Nine (9) and ten (10), in Block Eight (8), Plat of the Village of Bay View, Door County, Wisconsin.

Recording Area

Name and Return Address

Lori De Jardin
N8512 CTH A
Luxemburg, Wisconsin 54217

1200

281-12-10080904

Parcel Identification Number (PIN)

STATE OF WISCONSIN)
COUNTY OF DOOR) ss

Section 1. Lori De Jardin is the owner of the above-described property.

Section 2. Petroleum contaminated groundwater above NR 140 enforcement standards and soils above NR 720 residual contaminant levels of the Wisconsin Administrative Code exist(s) on this property.

Section 3. The owner hereby declares that all of the property described above is held and shall be held, conveyed or encumbered, leased, rented, used, occupied and improved subject to the following limitations and/or restrictions:

Anyone who proposes to construct or reconstruct a well on this property is required to contact the Department of Natural Resources' Bureau of Drinking Water and Groundwater, or its successor agency, to determine what specific prohibitions or requirements are applicable, prior to constructing or reconstructing a well on this property. No well may be constructed or reconstructed on this property unless applicable requirements are met.

Residual petroleum contaminated soil remains on this site. It has been shown that these levels are protective of health and the environment. If this contaminated soil is excavated in the future, it may be considered a solid waste and will need to be disposed in accordance with all applicable laws.

Any person who is or becomes owner of the property described above may request that the Wisconsin Department of Commerce, or its successor, issue a determination that the restrictions set forth in this covenant are no longer required.

That property owner shall provide any and all necessary information to the Department in order for the Department to be able to make a determination. Upon receipt of such a request, the Department shall determine whether or not the restrictions contained herein can be extinguished. Conditions under which a restriction may be extinguished will be determined in accordance with the site specific standards, rules and laws for this property. If the Department determines that the restrictions can be extinguished, an affidavit, with a copy of the Department's written determination, may be recorded to give notice that this restriction, or portions of this restriction are no longer binding. Any restriction placed upon this property shall not be extinguished without the Department's written determination.

IN WITNESS WHEREOF, the owner of the property has executed this document, this 22nd day of August, 2006.


Signature: Lori DeJardin

Printed Name: Lori DeJardin

Title: owner

Subscribed and sworn to before me
this 22nd day of August, 2006.

Ronda E. Diste
Notary Public, State of WI
My commission 11-24-2002



This document was drafted by the Wisconsin Department of Commerce.

606492

Document Number

**NOTICE OF CONTAMINATION TO
PROPERTY**

VOL 735 PAGE 37

RECEIVED FOR RECORD
REGISTER OF DEEDS
DOOR COUNTY

00 SEP 6 PM 2 20

Marilyn Jadin

Tract Indexed

16 00 Pd

Recording Area

Name and Return Address
Sturgeon Bay Waterfront
Redevelopment Authority
P.O. Box 47
Sturgeon Bay, Wisconsin 54235

Legal Description of the Property: In re:

Part of Lots 1 and 2, Block 9, Harris Addition to Bay View, City of Sturgeon Bay, and described as follows: Beginning at a point in the East line of Madison Street 177 feet North of the junction of said East line Madison Street with the North line of Maple Street said point of beginning also being the junction of said East line of Madison Street with the North line of alley, thence North 0°05' East along the said East line of Madison Street 84.5 feet, thence continuing along said East line of Madison Street North 4°17' East 64.5 feet, thence North 89°59' East 20 feet, thence South 28°07' East 79.29 feet, thence South 0°07' West 80 feet to a point in said North line of alley, thence along said North line of alley North 89°59' West 62.3 feet to point of beginning.

STATE OF WISCONSIN)
COUNTY OF DOOR) ss

281-24-15090102

Parcel Identification Number (PIN)

Section 1. Sturgeon Bay Waterfront Redevelopment Authority is the owner of the above-described property.

Section 2. One or more petroleum discharges have occurred at this property. Petroleum contaminated groundwater above NR 140 enforcement standards and soils above NR 720 residual contaminant levels of the Wisconsin Administrative Code exist(s) on this property.

Section 3. It is the desire and intention of the property owner to impose restrictions on the property which will make it unnecessary to conduct additional soil or groundwater remediation activities on the property at the present time. The owner hereby declares that all of the property described above is held and shall be held, conveyed or encumbered, leased, rented, used, occupied and improved subject to the following limitations and/or restrictions:

Petroleum contaminated soil remains on this property at depth in the vicinity of the former tank cavity and alleyway. Figure 1 represents the locations of petroleum contaminated soil above NR 720 residual contaminant levels of the Wisconsin Administrative Code. An impermeable cap or cover is the selected remedial action to address residual soil contamination on the property. Therefore, an impermeable cap or cover (i.e. concrete, asphalt) shall be maintained across this property until: 1). The soil is actively remediated or removed or; 2). It can be shown that the soil has naturally degraded to levels shown to be protective of the environment and human health. If subsurface work is done in the contaminated areas, the contamination shall be properly treated or disposed of in accordance with applicable laws.

Petroleum contaminated groundwater remains on this property. Natural attenuation has been approved by the Department of Natural Resources to remediate groundwater contamination exceeding NR140 ES Wis. Adm. Code. Figure 2 depicts the locations of petroleum contaminated groundwater above NR 140 ES of the Wis. Adm. Code.

Any person who is or becomes owner of the property described above may request that the Wisconsin Department of Commerce, or its successor, issue a determination that the restrictions set forth in this covenant are no longer required. That property owner shall provide any and all necessary information to the Department in order for the Department to be able to make a determination. Upon receipt of such a request, the Department shall determine whether or not the restrictions contained herein can be extinguished. Conditions under which a restriction may be extinguished will be determined in accordance with the site specific standards, rules and laws for this property. If the Department determines that the restrictions can be extinguished, an affidavit, with a copy of the Department's written determination, may be recorded to give notice that this restriction, or portions of this restriction are no longer binding. Any restriction placed upon this property shall not be extinguished without the Department's written determination.

IN WITNESS WHEREOF, the owner of the property has executed this document, this 1st day of September, 2000.

[When appropriate use the following clause]:

By signing this document, William Galligan and Jon Hanson acknowledge that William Galligan and Jon Hanson are duly authorized to sign this document on behalf of Sturgeon Bay Waterfront Redevelopment Authority.

Signature:

William C. Galligan

Signature:

Jon Hanson

Printed Name:

WILLIAM C. GALLIGAN

Printed Name:

Jon Hanson

Title:

VICE-CHAIRMAN

Title:

Secretary

Subscribed and sworn to before me
this 1st day of Sept., 2000.

Bonnie J. Heller

Notary Public, State of Wisconsin

My commission 5-12-2002

This document was drafted by the Wisconsin Department of Commerce.

606491

Document Number

NOTICE OF CONTAMINATION TO
PROPERTY

VOL 735 PAGE 33

RECEIVED FOR RECORD
REGISTER OF DEEDS
DOOR COUNTY

'00 SEP 6 PM 2 19

Marilyn Jadin

Tract Indexed

16 ⁰⁰ ₀₂

Recording Area

Name and Return Address

Sturgeon Bay Waterfront
Redevelopment Authority
P.O. Box 47
Sturgeon Bay, Wisconsin 54235

Legal Description of the Property: In re:

A tract of land located in Block Nine (9) of Harris' First addition to the City of Sturgeon Bay, in Section Seven (7), Township twenty-seven (27) North, Range Twenty-six (26) East, Door County, Wisconsin, bounded and described as follows: Commencing at the Southwest corner of said Block 9; thence East 62.3 feet along the South line of Block 9 to the point of beginning of lands to be described; thence continuing along said South line East 102.50 feet; thence 269.35 feet along the arc of a curve to the right whose chord bears North 18°46'23" West 268.78 feet (radius 1204.11 feet, I-12 ° 48'59"); thence North 81°41'41" West 42.43 feet to the Easterly right-of-way line of Madison Avenue; thence along said right-of-way line 115.64 feet along the arc of a curve to the left whose chord bears South 15°45'54" West 1115.32 feet (radius 448.49, I-14°46'23"); thence North 89°58'00" East 20.10 feet; thence South 28°12'33" East 79.03 feet; thence South 00°06'00" West 80.00 feet to the point of beginning. Said parcel contains 19,892 square feet.

STATE OF WISCONSIN)
) ss
COUNTY OF DOOR)

281-24-15090103
Parcel Identification Number (PIN)

Section 1. Sturgeon Bay Waterfront Redevelopment Authority is the owner of the above-described property.

Section 2. One or more petroleum discharges have occurred at this property. Petroleum contaminated groundwater above NR 140 enforcement standards and soils above NR 720 residual contaminant levels of the Wisconsin Administrative Code exist(s) on this property.

Section 3. It is the desire and intention of the property owner to impose restrictions on the property which will make it unnecessary to conduct additional soil or groundwater remediation activities on the property at the present time. The owner hereby declares that all of the property described above is held and shall be held, conveyed or encumbered, leased, rented, used, occupied and improved subject to the following limitations and/or restrictions:

Petroleum contaminated soil remains on this property at depth in the vicinity of the former tank cavity and alleyway. Figure 1 represents the locations of petroleum contaminated soil above NR 720 residual contaminant levels of the Wisconsin Administrative Code. An impermeable cap or cover is the selected remedial action to address residual soil contamination on the property. Therefore, an impermeable cap or cover (i.e. concrete, asphalt) shall be maintained across this property until: 1). The soil is actively remediated or removed or; 2). It can be shown that the soil has naturally degraded to levels shown to be protective of the environment and human health. If subsurface work is done in the contaminated areas, the contamination shall be properly treated or disposed of in accordance with applicable laws.

Petroleum contaminated groundwater remains on this property. Natural attenuation has been approved by the Department of Natural Resources to remediate groundwater contamination

exceeding NR140 ES Wis. Adm. Code. Figure 2 depicts the locations of petroleum contaminated groundwater above NR 140 ES of the Wis. Adm. Code.

Any person who is or becomes owner of the property described above may request that the Wisconsin Department of Commerce, or its successor, issue a determination that the restrictions set forth in this covenant are no longer required. That property owner shall provide any and all necessary information to the Department in order for the Department to be able to make a determination. Upon receipt of such a request, the Department shall determine whether or not the restrictions contained herein can be extinguished. Conditions under which a restriction may be extinguished will be determined in accordance with the site specific standards, rules and laws for this property. If the Department determines that the restrictions can be extinguished, an affidavit, with a copy of the Department's written determination, may be recorded to give notice that this restriction, or portions of this restriction are no longer binding. Any restriction placed upon this property shall not be extinguished without the Department's written determination.

IN WITNESS WHEREOF, the owner of the property has executed this document, this 1st day of September, 2000.

[When appropriate use the following clause]:

By signing this document, William Galligan and Jon Hanson acknowledge that William Galligan and Jon Hanson are duly authorized to sign this document on behalf of Sturgeon Bay Waterfront Redevelopment Authority.


Signature: William Galligan
Printed Name: WILLIAM C. GALLIGAN
Title: VICE-CHAIRMAN

Signature: Jon Hanson
Printed Name: Jon Hanson
Title: Secretary

Subscribed and sworn to before me
this 1st day of Sept., 2000.

Bonnie J. Hulse
Notary Public, State of Wisconsin
My commission 5-12-2002


This document was drafted by the Wisconsin Department of Commerce.



BRUNSWICK STATION SITE

(USGS 1981)

SCALE
1:24000



CONTOUR INTERVAL 10 FEET



LOCATION



ENVIROGEN

COST EFFECTIVE LEADERSHIP FOR A CLEANER ENVIRONMENT

2835 North Grandview Blvd.
Pewaukee, Wisconsin 53072-0090


SITE LOCATION
MAP

FORMER BRUNSWICK STATION SITE
STURGEON BAY, WISCONSIN

FIGURE NO.

1

DATE	
ENGINEER	
DATE	
ENGINEER	
REVISIONS:	
APPROVED BY:	
CHECKED BY:	
KMA	9/27/99
DRAWN BY:	
DRAWING NO.	95.513AD1



NOTE: THERE ARE STORM SEWER LINES IN THIS AREA, THEY WERE NOT MARKED.





ENVIROGEN
BEST PRACTICE LEADERSHIP FOR A CLEANER ENVIRONMENT
780 Lincoln Ave.
Green Bay, Wisconsin 54304


GROUNDWATER BENZENE
DISTRIBUTION (1/27/99)
FORMER BRUNSWICK STATION SITE
STURGEON BAY, WISCONSIN

2

DRAWING NO. 95.513L15 DRAWN BY: RRT 11/29/99 CHECKED BY: [Signature] APPROVED BY: [Signature] REVISIONS: ENGINEER DATE ENGINEER DATE



NOTE: THERE ARE STORM SEWER LINES IN THIS AREA. THEY WERE NOT MARKED.



- LEGEND**
- ⊕ MONITORING WELL
 - () ELEVATION IN FEET ABOVE MSL
 - / — ISOELEVATION CONTOUR
- NOTE:**
HYDRAULIC GRADIENT (dh/dl) = .01 ft/ft

TABLE 5

Groundwater Sample Laboratory Analytical Results
Curly's Cleaners Parking Lot Site
Sturgeon Bay, Wisconsin
May 27, 1999

Sample	Benzene	Ethyl benzene	MTBE	Toluene	1,2,4- TMB	1,3,5- TMB	Xylenes	n-butylbenzene	p-isopropyl- toluene	isopropyl- benzene	naphthalene	n-propylbenzene
GP-1	<0.27	<0.32	<0.32	<0.27	<0.22	<0.27	<0.67	<0.29	<0.24	<0.26	<0.35	<0.76
GP-3	X	<0.32	<0.32	<0.27	0.40	2.4	0.84	0.77	0.45	<0.26	<0.35	<0.76
GP-4	920	X	110	4.4	650	210	1,331	23	3.8	22	58	70
NR 140 ES	5	700	60	343	NS	NS	620	NS	NS	NS	40	NS
NR 140 PAL	0.5	140	12	68.6	NS	NS	124	NS	NS	NS	8	NS

Notes: All results are reported in ppb unless otherwise noted



Shading indicates value equals or exceeds the NR 140 enforcement standard
Cross hatching indicates value equals or exceeds the NR 140 preventive action limit

MTBE: Methyl t-butyl ether
TMB: Trimethylbenzene
ES: Enforcement standard
PAL: Preventive action limit
NS: No standard

Checked by: *[Signature]*
Approved by: *[Signature]*

TABLE 6
Geoprobe Groundwater Sample Laboratory Analytical Results
Former Brunswick Station Site
Sturgeon Bay, Wisconsin

0.85 13

Sample Location	Date	GRO (ppm)	Benzene	Ethylbenzene	Toluene	Total Xylenes	1,2,4-TMB	1,3,5-TMB	MTBE	Naphthalene
GP-3	08/28/96	51	XX	<1.0	<1.0	3.1	2.4	<1.0	XX	NA
GP-6	08/29/96	<50	<0.50	<1.0	<1.0	<3.0	<1.0	<1.0	XX	NA
GP-7	08/29/96	3,100	780	89	44	680	110	27	420	NA
GP-9	08/29/96	41,000	8,200	2,800	16,000	15,000	3,800	1,100	3,800	930
GP-10	08/29/96	420	XX	1.3	4.9	100	4.2	1.0	170	1.5
GP-12	08/30/96	56,000	24	55	2.6	310	370	130	<1.0	XX
GP-13	08/30/96	43,000	6,600	1,100	7,500	6,800	1,200	350	270	NA
NR 140 Enforcement Standard		NS	5	700	343	620	NS	NS	60	40
NR 140 Preventive Action limit		NS	0.5	140	68.6	124	NS	NS	12	8
										31
										310

Notes:

All results are reported in ppb unless otherwise noted

Shading indicates value equals or exceeds the NR 140 enforcement standard

XX Cross-Section indicates value equals or exceeds the NR 140 preventive action limit

GRO: Gasoline range organics
TMB: Trimethylbenzene
MTBE: Methyl t-butyl ether
NA: Not analyzed
NS: No standard

Checked by: *ILS*
Approved by: *Lawrence*

TABLE 8
Groundwater Sample Laboratory Analytical Results
Former Brunswick Station Site
Sturgeon Bay, Wisconsin

Sample Location	Date	GRO (ppm)	DRO (ppm)	Benzene	Ethylbenzene	Toluene	Total Xylenes	1,2-DCA	MTBE	1,2,4-TMB	1,3,5-TMB	Naphthalene	Dissolved Lead
MW-1	08/30/96	<50	<100	<0.50	<1.0	<1.0	<3.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.5
	11/05/96	<50	<100	<0.50	<1.0	<1.0	<3.0	NA	3.5	<1.0	<1.0	NA	NA
	03/04/97	<50	<100	<0.13	<0.22	<0.20	<0.23	NA	<0.16	<0.22	<0.29	NA	NA
	05/08/97	<100	<100	<0.21	<0.21	<0.48	<0.58	NA	<0.21	<0.32	<0.27	NA	NA
MW-1A	04/15/98	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	11/10/98	NA	NA	<0.31	<0.26	<0.48	<1.0	NA	<0.66	<0.27	<0.18	<0.49	NA
	01/27/99	NA	NA	<0.13	<0.22	0.35	<0.23	NA	<0.16	<0.22	<0.29	NA	NA
	08/30/96	8,900	9,000	1,200	210	1,700	1,600	<50	520	460	140	100	<1.5
MW-2	11/05/96	40,000	24,000	9,100	760	12,000	5,700	NA	3,300	680	220	NA	NA
	03/04/97	13,000	8,600	3,200	660	2,100	2,200	NA	1,200	340	110	NA	NA
	05/08/97	6,300	3,800	1,100	310	1,200	1,400	NA	170	280	110	NA	NA
	04/15/98	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	11/10/98	NA	NA	1,700	240	990	1,000	NA	<13	250	76	70	NA
NR 140 Enforcement Standard		NS	NS	5	343	700	620	5	60	NS	NS	40	15
NR 140 Preventive Action Limit		NS	NS	0.5	68.6	140	124	0.5	12	NS	NS	8	1.5

(Continued)

Notes: All results are reported in ppb unless otherwise noted

Shading indicates value equals or exceeds the NR 140 enforcement standard

Cross-Section indicates value equals or exceeds the NR 140 preventive action limit



DRO: Diesel range organics
 GRO: Gasoline range organics
 TMB: Trimethylbenzene
 MTBE Methyl t-butyl ether
 NA: Not analyzed
 NS: No standard

210
 260
 210
 240
 160

Checked by: *[Signature]*
 Approved by: *[Signature]*

TABLE 8 (Continued)
Groundwater Sample Laboratory Analytical Results
Former Brunswick Station Site
Sturgeon Bay, Wisconsin

2.1

200 150

Sample Location	Date	GRO (ppm)	DRO (ppm)	Benzene	Ethylbenzene	Toluene	Total Xylenes	1,2-DCA	MTBE	1,2,4-TMB	1,3,5-TMB	Naphthalene	Dissolved Lead
MW-3	08/30/96	12,000	6,000	54,000	390	110	2,000	<20	3,300	450	120	75	NA
	11/05/96	5,200	4,000	2,600	130	22	490	NA	1,800	120	49	NA	NA
	03/04/97	5,500	2,900	2,400	200	26	1,240	NA	1,700	160	68	NA	NA
	05/08/97	13,000	4,400	62,000	360	160	1,800	NA	2,800	380	160	NA	NA
MW-3A	04/15/98	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	11/10/98	NA	NA	1,900	280	<9.6	110	NA	1,100	73	11	NA	NA
	01/27/99	NA	NA	790	60	<4.0	4.6	NA	750	9.9	<5.8	NA	NA
MW-4	08/30/96	710	320	390	<5.0	<5.0	25	<5.0	570	<5.0	<5.0	<5.0	<1.5
	11/05/96	370	910	76	<1.0	<1.0	4.9	NA	390	1.1	<1.0	NA	NA
	03/04/97	710	2,000	200	0.65	0.82	12	NA	660	3.7	1.5	NA	NA
	05/08/97	520	220	180	0.61	1.3	17	NA	370	8.4	3	NA	NA
MW-4A	04/15/98	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	11/10/98	NA	NA	10	<0.52	1.0	12	NA	140	1.5	<0.36	<0.98	NA
	01/27/99	NA	NA	NA	<0.22	<0.20	0.38	NA	110	<0.22	<0.29	NA	NA
NR 140 Enforcement Standard		NS	NS	5	343	700	620	5	60	NS	NS	40	15
NR 140 Preventive Action Limit		NS	NS	0.5	68.6	140	124	0.5	12	NS	NS	8	1.5

Notes: All results are reported in ppb unless otherwise noted



DRO: Diesel range organics
 GRO: Gasoline range organics
 TMB: Trimethylbenzene
 MTBE: Methyl t-butyl ether
 NA: Not analyzed
 NS: No standard

Shading indicates value equals or exceeds the NR 140 enforcement standard
 Cross-Section indicates value equals or exceeds the NR 140 preventive action limit

4.2

280

540

490

(Continued)

36

Checked by: *[Signature]*
 Approved by: *[Signature]*







TABLE 8 (Continued)
Groundwater Sample Laboratory Analytical Results
Former Brunswick Station Site
Sturgeon Bay, Wisconsin



Sample Location	Date	GRO (ppm)	DRO (ppm)	Benzene	Ethylbenzene	Toluene	Total Xylenes	1,2-DCA	MTBE	1,2,4-TMB	1,3,5-TMB	Naphthalene	Dissolved Lead
MW-10	04/15/98	NA	NA	<0.32	0.48	0.88	<1	NA	1.7	1.0	<0.64	NA	NA
	11/10/98	NA	NA	<0.10	<0.25	<0.10	<0.25	NA	1.8	<0.10	<0.10	<0.10	NA
	01/27/99	NA	NA	<0.13	<0.22	<0.20	<0.23	NA	2.5	<0.22	<0.29	NA	NA
MW-11	04/15/98	NA	NA	0.33	0.48	1.2	1.0	NA	0.46	1.2	0.7	NA	NA
	11/10/98	NA	NA	<0.10	<0.25	<0.10	<0.25	NA	1.8	<0.10	<0.10	<0.10	NA
	01/27/99	NA	NA	<0.13	<0.22	<0.20	<0.23	NA	0.99	<0.22	<0.29	NA	NA
MW-12	04/15/98	NA	NA	<0.32	<0.34	<0.35	<1.0	NA	<0.31	<0.35	<0.64	NA	NA
	11/10/98	NA	NA	<0.31	<0.26	<0.48	<1.0	NA	<0.66	<0.27	<0.18	<0.49	NA
	01/27/99	NA	NA	<0.13	<0.22	<0.20	<0.23	NA	1.0	<0.22	<0.29	NA	NA
NR 140 Enforcement Standard		NS	NS	5	343	700	620	5	60	NS	NS	40	15
NR 140 Preventive Action Limit		NS	NS	0.5	68.6	140	124	0.5	12	NS	NS	8	1.5

Notes: All results are reported in ppb unless otherwise noted

Shading indicates value equals or exceeds the NR 140 enforcement standard

Cross-Section indicates value equals or exceeds the NR 140 preventive action limit

 DRO: Diesel range organics
 GRO: Gasoline range organics
 TMB: Trimethylbenzene
 MTBE Methyl t-butyl ether
 NA: Not analyzed
 NS: No standard

Checked by: 
 Approved by: 

(Continued)